

Employer's Delivery Team Construction Vibration Monitoring Report

M9 Junction 1a Contract (October 2012)





FORTH REPLACEMENT CROSSING

EMPLOYER'S DELIVERY TEAM CONSTRUCTION VIBRATION MONITORING REPORT

M9 JUNCTION 1A CONTRACT (October 2012)

Revision Status

Revision	evision Date Des		Author	Approved for Use
0	December 2012	Original	DGC/RML	AMM

FORTH REPLACEMENT CROSSING

EMPLOYER'S DELIVERY TEAM CONSTRUCTION VIBRATION MONITORING REPORT

CONTENTS

1.	INTRODUCTION	. 3
2.	M9 J1A CONTRACT VIBRATION MONITORING	. 4
	ADDENDIY A MO 14 A CONTRACT CONSTRUCTION VIRRATION CHARTS	

1. INTRODUCTION

1.1 This report sets out the results of the construction vibration monitoring undertaken on the M9 Junction 1a Contract in October 2012 as part of the Forth Replacement Crossing project.

2. M9 J1A CONTRACT VIBRATION MONITORING

VIBRATION MONITORING LOCATIONS

2.1 Continuous vibration monitoring was carried out at fixed monitor locations in October 2012 as outlined in Table 2.1 below. The main construction activities carried out adjacent to the monitor locations are also listed.

Monitoring Monitoring		Main Construction Activities		
Location	Period			
93/95 King Edwards Way (CNV02)	October 2012	Pavement surfacing works		
15-17 Buie Rigg (CNV07)	October 2012	 Earthworks & SUDS pond excavation Pavement works on eastbound diverge slip Pavement works on eastbound merge slip Pavement works on M9 Mainline Concrete pours at M901 Overbridge Erection of Gantry 11 Traffic management movement of Varioguard 		
8 Kirklands Park Grove (CNV16)	October 2012	 Safety Barrier works at M9 Spur Pavement works on northbound M9 Spur Concrete pours at Newmains Bridge Traffic management on southbound M9 Spur 		

Table 2.1 Long Term Monitoring Locations – October


VIBRATION MONITORING RESULTS

- 2.2 The results of the M9 J1a Contract construction vibration monitoring are provided in chart format in Appendix A of this report.
- 2.3 The charts show the Vibration Dose Values (VDV) and Peak Particle Velocities (PPV) recorded at receptors. VDV levels are recorded in order to monitor the potential for disturbance to the occupants of buildings (as discussed in BS 6472) and PPV values are recorded in order to monitor the potential for damage to buildings (as discussed in BS 7385).

- 2.4 The charts indicate that all construction activities in the period were carried out in accordance with the vibration thresholds set out in the project Code of Construction Practice.
- 2.5 One exceedance of the VDV threshold level was recorded in October 2012. The exceedance was investigated and the Contractor found that no construction activates were being carried out in the area at the time of the exceedance. The exceedance is therefore not attributed to construction works.
- 2.6 No exceedances of the PPV threshold level were recorded in the month of October.

APPENDIX A - M9 J1A CONTRACT CONSTRUCTION VIBRATION CHARTS

Measured highest daytime Peak Particle Velocity (PPV), 93/95 King Edwards Way (CNV02) Measurement period 1st October 2012 to 31st October 2012



Construction PPV Thresholds


Daily PPV thresholdfor intermittentconstruction

Daily PPV thresholdfor continuousconstruction

Measured VDV

- Daily highest PPV (z-axis)
- (n) = Investigation Report Number

Measured highest night-time Peak Particle Velocity (PPV), 93/95 King Edwards Way (CNV02) Measurement period 1st October 2012 to 31st October 2012



Construction PPV Thresholds

Daily PPV thresholdfor intermittentconstruction


Daily PPV thresholdfor continuousconstruction

Measured VDV

■ Daily highest PPV (z-axis)

(n) = Investigation Report Number

Measured daytime (07:00-23:00) Vibration Dose Values (VDV), 93/95 King Edwards Way (CNV02) Measurement period 1st October 2012 to 31st October 2012



Construction VDV Threshold

Daily daytime VDV

threshold for
residential dwellings


Measured VDV

- Daily daytime VDV (z-axis)
- (n) = Investigation Report Number

Note: The horizontal axes often show high vibration levels caused by spurious 'localised' events which are not attributable to construction works, whilst the vertical axis appears much less affected.

Therefore the results from only the vertical dataset are presented, as a more reliable indicator of the prevailing vibration climate at this location.

Measured night time (23:00-07:00) Vibration Dose Values (VDV), 93/95 King Edwards Way (CNV02) Measurement period 1st October 2012 to 31st October 2012



A transfer function equivalent to doubling the night-time VDV measurements has been applied to obtain values representative of an upstairs, mid-floor receptor location. VDV threshold for Education establishments, offices and similar is 0.40ms^{-1.75} and Commercial is 0.80ms^{-1.75}. Therefore it may be necessary to adjust the threshold displayed on the graph if buildings other than residential dwellings are being assessed.


Construction VDV Threshold

Daily night time VDVthreshold for residential dwellings

Measured VDV

- Daily night time VDV (z-axis)
- (n) = Investigation Report Number

Measured highest daytime Peak Particle Velocity (PPV), 15-17 Buie Rigg (CNV07) Measurement period 1st October 2012 to 31st October 2012



Construction PPV Thresholds

Daily PPV thresholdfor intermittentconstruction

Daily PPV threshold


for continuous construction

Measured VDV

■ Daily highest PPV (z-axis)

(n) = Investigation Report Number

Measured highest night-time Peak Particle Velocity (PPV), 15-17 Buie Rigg (CNV07) Measurement period 1st October 2012 to 31st October 2012



Construction PPV Thresholds


Daily PPV thresholdfor intermittentconstruction

Daily PPV thresholdfor continuous construction

Measured VDV

- Daily highest PPV (z-axis)
- (n) = Investigation Report Number

Measured daytime (07:00-23:00) Vibration Dose Values (VDV), 15-17 Buie Rigg (CNV07) Measurement period 1st October 2012 to 31st October 2012



Construction VDV Threshold

Daily daytime VDVthreshold for residential dwellings


Measured VDV

- Daily daytime VDV (z-axis)
- (n) = Investigation Report Number

Note: The horizontal axes often show high vibration levels caused by spurious 'localised' events which are not attributable to construction works, whilst the vertical axis appears much less affected.

Therefore the results from only the vertical dataset are presented, as a more reliable indicator of the prevailing vibration climate at this location.

Measured night time (23:00-07:00) Vibration Dose Values (VDV), 15-17 Buie Rigg (CNV07) Measurement period 1st October 2012 to 31st October 2012



Construction VDV Threshold

Daily night time VDVthreshold for residential dwellings


Measured VDV

- Daily night time VDV (z-axis)
- (n) = Investigation Report Number

Note: The horizontal axes often show high vibration levels caused by spurious 'localised' events which are not attributable to construction works, whilst the vertical axis appears much less affected.

Therefore the results from only the vertical dataset are presented, as a more reliable indicator of the prevailing vibration climate at this location.

Measured highest daytime Peak Particle Velocity (PPV), 8 Kirklands Park Grove (CNV16) Measurement period 1st October 2012 to 31st October 2012



Construction PPV Thresholds

Daily PPV thresholdfor intermittentconstruction


Daily PPV thresholdfor continuous construction

Measured VDV

■ Daily highest PPV (z-axis)

(n) = Investigation Report Number

Measured highest night-time Peak Particle Velocity (PPV), 8 Kirklands Park Grove (CNV16) Measurement period 1st October 2012 to 31st October 2012



Construction PPV Thresholds

Daily PPV thresholdfor intermittentconstruction


Daily PPV thresholdfor continuous construction

Measured VDV

■ Daily highest PPV (z-axis)

(n) = Investigation Report Number

Measured daytime (07:00-23:00) Vibration Dose Values (VDV), 8 Kirklands Park Grove (CNV16) Measurement period 1st October 2012 to 31st October 2012



Construction VDV Threshold

Daily daytime VDV

threshold for
residential dwellings

Measured VDV


■ Daily daytime VDV (z-axis)

(n) = Investigation Report Number

Note: The horizontal axes often show high vibration levels caused by spurious 'localised' events which are not attributable to construction works, whilst the vertical axis appears much less affected.

Therefore the results from only the vertical dataset are presented, as a more reliable indicator of the prevailing vibration climate at this location.

Measured night time (23:00-07:00) Vibration Dose Values (VDV), 8 Kirklands Park Grove (CNV16) Measurement period 1st October 2012 to 31st October 2012



Construction VDV Threshold

Daily night time VDV
threshold for
residential dwellings

Measured VDV

■ Daily night time VDV (z-axis)

(n) = Investigation Report Number

Note: The horizontal axes often show high vibration levels caused by spurious 'localised' events which are not attributable to construction works, whilst the vertical axis appears much less affected.

Therefore the results from only the vertical dataset are presented, as a more reliable indicator of the prevailing vibration climate at this location.

A transfer function equivalent to doubling the night-time VDV measurements has been applied to obtain values representative of an upstairs, mid-floor receptor location. VDV threshold for Education establishments, offices and similar is 0.40ms^{-1.75} and Commercial is 0.80ms^{-1.75}. Therefore it may be necessary to adjust the threshold displayed on the graph if buildings other than residential dwellings are being assessed.



Project Title:

Contractor:

FORTH REPLACEMENT CROSSING

M9 Junction 1A

Date:

SRB 22-10-12

NER. 169

208

Project

Number:

QUALITY MANAGEMENT SYSTEM

VIBRATION EXCEEDENCE REPORT

Summary of Finding(s): October 20th - CNV02

Exceedences 355: Maximum VDV: 0.57 at 17.30 on Saturday

An analysis was carried out using the following data:

- Recorded Vibration Logs
- Vibration type
- Site Diaries / Weather Data
- Inspections by Senior Engineer (Roland Tarrant)

Findings:

Analysis of the site diary shows that no works were carried out in this area at this time by SRB.

Therefore it is considered unlikely that noise from the construction activities caused the exceedence.

Corrective Action Required:

I	V	laintain	current	: moni	toring	and	surveil	lance	levels.

SignatureR	toland Tarrant	Date	.22-10-12

NER Closed

Works have been inspected and completed as described above.

SignatureSeamus O'Brien............Date22-10-12...

Project Manager / Assist Project Manager

