

Contractor



Project FORTH REPLACEMENT CROSSING

Document title

VIBRATION MONITORING REPORT APRIL 2016

00	11/05/16	First draft	MRN	SWR	SWR
Rev	Rev. Date	Purpose of revision	Made	Reviewed	Approved

Document status

FOR REVIEW

Made by Michael Richardson	Checked By: Steven Westwater		
Initials: MRN	Initials: SWR		
Document number			
REP-00277	00		

This document is intellectual property of FCBC Construction JV. Copying, distribution, usage, and information on contents of this are forbidden unless explicitly authorized.



Contents

- 1. Introduction
- 2. Monitoring Summary
- 3. Conclusion

Appendices:

Appendix A: Vibration Assessments from Relevant PCNVs

Appendix B: PPV and VDV Graphs



INTRODUCTION

- 1.1. Monitoring of construction vibration is being undertaken by FCBC during the construction of the new Forth Crossing and associated road network. This report covers the month of April 2016. The objective of this report is to detail the vibration monitoring that has been undertaken across the site during this period, which has been done so in accordance with the Code of Construction Practice (CoCP), and Noise and Vibration Management Plan (NVMP).
- 1.2. FCBC carefully risk assesses noise & vibration likely to result from all construction activities, through the production of Plans for Control of Noise & Vibration (PCNVs). During the preparation of PCNVs, vibration prediction assessments are made. These assessments illustrate that no construction plant, equipment or methodology to be used by FCBC are envisaged to induce any levels of vibration at sensitive receptors that would exceed the vibration threshold levels stated in the CoCP. These assessments/predictions have been validated by means of the vibration monitoring results displayed in this report.



2. MONITORING SUMMARY

- 2.1. Due to the location and sensitivity of vibration monitoring equipment, the exceedances presented in the graphs included in the appendices of this report do not represent levels generated by construction, but rather show local interference around the monitoring equipment. This can include, for example, doors being slammed, or indeed any significant movements occurring close to the monitoring equipment.
- 2.2. According to the BS5228-2 (2009) there is minimal documented proof of actual damage to structures or their finishes resulting from construction, and damage resulting solely from well-controlled construction and demolition vibrations is rare. There are many other mechanisms which cause damage, especially in decorative finishes, and it is often incorrectly concluded that vibrations from construction and demolition sites are to blame. In many cases it is not possible to ascertain the exact source of vibration, though it is possible to rule out construction as a source on an activity basis.
- **2.3.** The works carried out in each of the various construction work areas as well as the related vibration assessments are summarised in Appendix A.
- 2.4. Considering the distances between the various construction work areas and sensitive receptors as well as working methods utilised, the risk of any damage to structures or nuisance to residents occurring as a result FCBC construction related vibration is highly unlikely.
- **2.5.** The number of threshold exceedances at the various vibration monitoring stations during the period in question are shown in Table 1 below.



Table 1: Exceedances of thresholds set out in the CoCP

April 2016

April 2010	PPV Exceedan	VDV Exceedance		
Location	Continuous (5 mm.s ⁻¹)	Intermittent (10 mm.s ⁻	Day (0.4 m.s ⁻	Night (0.2 m.s ^{-1.75})
Linn Mill	6	1	0	0
Butlaw Fisheries	0	0	0	0
Clufflat Brae	9	10	0	0
Dundas Home Farm	0	0	0	0
Echline	0	0	0	0
Inchgarvie Lodge	3	2	0	0
Scotstoun	0	0	0	0
Springfield	5	6	0	0
Tigh-Na- Grian	0	0	0	0
Whinnyhill	3	2	0	0

- **2.6.** Peak Particle Velocity (PPV) is used to measure vibration through a solid surface. When a vibration is measured, the point at which the measurement takes place can be considered to have a particle velocity. This particle vibration will take place in three dimensions (x, y and z).
- 2.7. The Peak Particle Velocity is the highest velocity that is recorded during a particular event, and as such is appropriate for the measurement of activities such as blasting, piling and compacting. The thresholds for the Forth Replacement Crossing are 5 mm.s⁻¹ for continuous construction (e.g. piling), and 10 mm.s⁻¹ for intermittent construction (e.g. blasting).
- 2.8. These thresholds are set to protect against building damage. For this monitoring period, all the exceedances have been investigated thoroughly and appear to have been generated as a result of standalone, instantaneous events arising from local interferences, the exact source of which remains unknown.



- 2.9. Vibration Dose Value (VDV) is a metric used in vibration monitoring. It is calculated by taking the fourth root of the integral of the fourth power of acceleration after it has been frequency-weighted. The frequency-weighted acceleration is measured in m.s⁻² and the time period over which the VDV is measured is in seconds. This yields VDVs in m.s^{-1.75}.
- **2.10.** The vibration dose value (VDV), a cumulative measurement of the vibration level received over an 8-hour or 16-hour period, is recommended in BS 6472 as the appropriate measure to evaluate human exposure to vibration in buildings in residential and other uses.
- **2.11.** During the monitoring period, vibratory rollers and whacker plates were used intermittently at several locations around the site however no exceedances were recorded as a result of the use of this equipment.,.
- **2.12.** Detailed investigation of all other exceedances (i.e. review of PPV levels over 30 seconds periods) has shown that each resulted from isolated, non-construction related events, which occurred close to the monitoring station.
- **2.13.** Within the Appendix B, there are gaps of missing data in the PPV and VDV of Dundas graphs. These occurred due to a power supply issue that has since been resolved on the 11th of May.



3. CONCLUSION

- **3.1.** Considering the distance between FCBC construction works and sensitive receptors, and the methods of working utilised, the risk of damage to structures or nuisance to residents resulting from vibration is highly unlikely.
- **3.2.** Due to the location and sensitivity of vibration monitoring equipment, the exceedances presented in the graphs included in the appendices of this report are unlikely to be generated by construction, but rather show local interference around the monitoring equipment.



APPENDIX A – MONITORING LOCATIONS & VIBRATION ASSESSMENTS FROM RELEVANT PCNVs



Table 2: Monitoring Locations

Ref.	Monitoring Location	Crossing or Network	Main Construction Activities During April 2016
M1	Whinny Hill	Network	 Earthworks/Fill placement Hope Street roadworks FT03 & FT04 works FT09 works FT19 Works Main carriageway Roadworks Rock crushing
M3	Tigh-Na-Grian	Crossing	 Central Tower rebar, formwork, concreting works deck section lifts and stay cable installation works North Tower rebar, formwork, concreting works deck section lifts and stay cable installation works Pier N1 & N2 bearing works AVN Rebar and concrete works
M7	Butlaw Fisheries	Crossing	 Central Tower rebar, formwork, concreting works deck section lifts and stay cable installation works South Tower rebar, formwork, concreting works deck section lifts and stay cable installation works Pier S1 rebar, formwork & concrete works Pier S2 rebar, formwork & concrete works AVS rebar & concrete deck works
M10	Inchgarvie Lodge	Crossing	 Central Tower rebar, formwork, concreting works deck section lifts and stay cable installation South Tower rebar, formwork, concreting works deck section lifts and stay cable installation Pier S1 rebar, formwork & concrete works Pier S2 rebar, formwork & concrete works AVS rebar & concrete deck works Main carriageway roadworks
M11	Linn Mill	Network (close proximity to Crossing)	 AVS rebar & concrete deck works Main carriageway roadworks No night time or Sunday construction in the vicinity
M13	Clufflat Brae	Crossing	 AVS rebar & concrete deck works Main carriageway roadworks No night time or Sunday daytime construction in the vicinity
M14	Springfield	Network	 AVS rebar & concrete deck works Main carriageway roadworks Earthworks south abutment area No night time or Sunday daytime construction in the vicinity
M15	Echline	Network	AVS rebar & concrete deck works Earthworks south abutment area Main carriageway roadworks
M16	Scotstoun	Network	 Footpath works Utility works B800 North road works including bridge works ESQ11 rebar works



			Mainline roadworks
M17	Dundas Home Farm	Network	 Utility works B800 south roadworks including bridge works ESQ11 rebar works Mainline roadworks

Table 2: The main construction activities undertaken in the locality of each of the vibration monitors during the period of April 2016.

Table 3: PCNV Predicted PPV & VDV Levels

	Minimum distance	from work areas (m)	Type of vibration emitting	Worst case predicted vibration levels		
Monitor	Day (07:00-19:00)	Night (19:00-07:00)	plant/activity operated at nearest work areas	PPV (mm/s)	eVDV (m.s ^{-1.75})	
Butlaw Fisheries	130	160	Roller/Whacker	0.44	0.23	
Clufflat Brae	40	90	Roller/Whacker	2.44	0.37	
Dundas	75	2000	Roller/Whacker	0.98	0.33	
Echline	40	1000	Roller/Whacker	2.44	0.37	
Inchgarvie Lodge	50	40	Roller/Whacker	1.77	0.33	
Linn Mill	60	250	Roller/Whacker	1.36	0.33	
Scotstoun	40	2000	Roller/Whacker	2.44	0.37	
Springfield	50	300	Roller/Whacker	1.77	0.33	
Tigh-Na-Grian	200	200	N/A	-	-	
Whinny Hill	180	1800	N/A	-	-	

Table 3: The distances from vibration monitors to the closest work areas for both day and night time periods. It also lists worst case PPV and eVDV calculations exhibited at the vibration monitors, resulting from the maximum vibration inducing plant operated at the nearest work areas.


Notes on Table 3

- All plant used during construction activities has been assessed with respect to vibration. The only plant utilised over the period in question considered to generate appreciable levels of vibration was a vibratory roller and a whacker plate (NOTE: Hydraulic rock breakers which typically generate 4.5mm/s @ 5m, 0.4mm/s @ 20m, 0.1mm/s @ 50m have been discounted due to the distances of use from the closest receptors).
- Vibratory rollers were not operated within 20m of any sensitive receptor.
- Whacker plates were not utilised within 40m of any occupied sensitive receptor.
- All roller eVDV values in the table above are based on the worst case scenario of a vibratory roller remaining in continuous operation for 2 hours an average distance (100m) from the nearest occupied receptors.
- All whacker plate eVDV values in the table above are based on the worst case scenario of a whacker plate remaining in continuous operation for 2 hours a minimum distance from the nearest receptor.




APPENDIX B – VIBRATION GRAPHS























Exceedances on the 2nd, 3rd, 4th, 5th, 7th, 12th, 13th, 14th, 16th, 20th, 22nd, 25th, and 29th of April have been investigated and found to be caused by individual isolated events that are unlikely to have been construction related activities (graph above from the 07/04/2016).




Exceedances on the 15th, 17th, 21st and 24th of April have been investigated and found to be caused out with construction working hours and therefore it is unlikely that construction related activity was the cause of these (graph above from the 15/04/2016).




Exceedance on the 27th of April has been investigated and found to be caused by the Environmental department carrying out monitor maintenance within the location of the vibration monitor.
















Data missing from the 6th to the 30th of April was caused by power issue at the monitor location. This has since been resolved on the 11th of May.






Data missing from the 6th to the 30th of April was caused by power issue at the monitor location. This has since been resolved on the 11th of May.






Data missing from the 6th to the 30th of April was caused by power issue at the monitor location. This has since been resolved on the 11th of May.























Exceedances on the 5th and 19th of April have been investigated and found to be caused by individual isolated events that are unlikely to have been construction related activities (graph above from the 05/04/2016).




Exceedances on the 9th, 13th and 20th of April have been investigated and found to be caused out with construction working hours and therefore it is unlikely that construction related activity was the cause of these (graph above from the 09/04/2016).

During this period the resident at the property, where the monitor is situated, has ongoing private construction works. It is likely that exceedances within the graph above were caused by the works on the property rather than the construction of the new crossing and supporting infrastructure.



















Exceedances on the 4th, 5th, 9th, 11th, 20th, and 27th of April have been investigated and found to be caused by individual isolated events that are unlikely to have been caused by construction related activities (graph above from the 09/04/2016). During this period there was minimal plant in the vicinity of this location.




Exceedance on the 18th of April have been investigated and found to have occured outwith construction working hours and therefore it is unlikely that construction related activity was the cause of these (graph above from the 18/04/2016).




































Exceedances on the 1st, 4th, 5th, 14th, 16th, 18th, 20th, 22nd and 27th of April have been investigated and found to be individual isolated events that are unlikely to have been caused by construction related activities (graph above from the 04/04/2016). During this period there was an increase of activity from the resident in his garden in which the monitor is situated. Due to this there is a likelihood that this activity is what has been picked up on the monitor (closest works to the monitor was approximately 290m away with no vibratory plant in use with the exception of a concrete poker on AVS).

Exceedances on the 10th and 17th of April have been investigated and found to have occured outwith construction working hours and therefore it is unlikely that construction relate activity was the cause.



































Exceedances on the 10th, 16th and 17th of April have been investigated and found to have occured outwith construction working hours and therefore it is unlikely that construction related activities was the cause. (graph above from the 16/04/2016).



Exceedance on the 11th of April has been investigated and found to be caused by AQM carrying out maintenance and calibration to the Air quality monitors. Due to the close proximity of the air quality monitor and the vibration monitor, movement by the calibration engineer was picked up on the vibration monitor.



Exceedance on the 29th of April has been investigated and found to be caused by individual isolated events that are unlikely to have been caused by construction related activities (graph above from the 29/04/2016).



