



Photograph 1: Disruption to A83 by debris flow



Photograph 2: Looking downhill onto the A83 at the lower section of run-out channel

Appendix C – Debris Flow Photographs



Photograph 3: Undercutting of A83 by debris flow and surface water erosion



Photograph 4: Debris flow channel below A83. New channel formed by debris flow on left of picture. Previous erosion from culvert on right of picture.

Appendix C – Debris Flow Photographs