




Note
Refer to Figure 6.1 for location of
photomontages




4. Winter - Existing situation photograph - Looking south west from the West Highland Way



4. Winter - Photomontage with proposed scheme - Looking south west from the West Highland Way



4. Summer - Existing situation photograph - Looking south west from the West Highland Way



4. Summer - Photomontage with proposed scheme - Looking south west from the West Highland Way



Scott Wilson Ltd
23 Chester Street
Edinburgh
EH1 1JN
Tel: 0151 225 1200
www.scotwilson.com

A82 Pulpit Rock


September 2010

Figure 6.4
Photomontages


This document has been prepared in accordance with the scope of Scott Wilson's appointment with its client and is subject to the terms of that appointment. Scott Wilson accepts no liability for any use of this document other than by its client and only for the purposes for which it was prepared and provided.

© Scott Wilson Ltd


Note
Refer to Figure 6.1 for location of
photomontages




4.5. Winter - Existing situation photograph - Looking west adjacent to the West Highland Way



4.5. Winter - Photomontage with proposed scheme - Looking west adjacent to the West Highland Way



4.5. Summer - Existing situation photograph - Looking west adjacent to the West Highland Way



4.5. Summer - Photomontage with proposed scheme - Looking west adjacent to the West Highland Way


Note
Refer to Figure 6.1 for location of photomontages




8. Existing situation photograph - Looking north west from the A82



8. Photomontage with proposed scheme - Looking north west from the A82



10. Existing situation photograph - Looking east adjacent to Pulpit Rock



10. Photomontage with proposed scheme - Looking east adjacent to Pulpit Rock

This document has been prepared in accordance with the scope of Scott Wilson's appointment with its client and is subject to the terms of that appointment. Scott Wilson accepts no liability for any use of this document other than by its client and only for the purposes for which it was prepared and provided.

© Scott Wilson Ltd




Scott Wilson Ltd
23 Chester Street
Edinburgh
EH1 1JN
Tel: 0151 725 1200
www.scottwilson.com


A82 Pulpit Rock

September 2010

Figure 6.4
Photomontages



13. Existing situation photograph - Looking south east from Stuckendroin Farm House



13. Photomontage with proposed scheme - Looking south east from Stuckendroin Farm House

Note
Refer to Figure 6.1 for location of photomontages

| | |
|---|--|
|  |  Scott Wilson Ltd 23 Chester Street Edinburgh EH1 1ES Tel: 0151 225 1200 www.scotwilson.com |
| A82 Pulpit Rock | September 2010 |

Figure 6.4
Photomontages

This document has been prepared in accordance with the scope of Scott Wilson's appointment with its client and is subject to the terms of that appointment. Scott Wilson accepts no liability for any use of this document other than by its client and only for the purposes for which it was prepared and provided.

© Scott Wilson Ltd